



# RWX 1000

## ADF WELDING GOOGLES

JASIC TECHNOLOGIES AMERICA INC 25503  
74th Ave S, Kent, WA 98032 Ph:  
253-859-6277, Fax: 253-859-6286  
sales@razorweld.com

### TECHNICAL SPECIFICATIONS

Filter Dimensions: 171.5x77.5mm ( 6.75" x 3.05")  
View Size: 110x40mm (4.33" x 1.57")  
Arc Sensors: 2  
Classification: 1/1/1/2  
Light State: 3  
Dark State: 5-9 / 9-13  
UV/IR Protection: DIN15  
Time from Light to Dark: 0.08ms  
Time from Dark to Light: 0.1-0.9s  
Sensitivity Delay: Adjustable (External)  
Power Supply: Solar Cells & CR2450 Replaceable Battery  
Warranty: 2 Years  
Operating Temperature: -10 °C to 65 °C (14 - 149 Degrees F)  
Storage Temperature: -20 °C to 85 °C (-4 - 176 Degrees F)  
Shade Control: Yes (External)  
Grind Mode: Yes (External)  
Minimum TIG Amperage: 5A  
Sleep and Wake up Detection feature  
Standards: AS/NZS 1337.1:2010, AS/NZS 1338.1:2012, CE, ANSI, CSA



### FEATURES:

#### LIGHTWEIGHT & COMPACT

Allows welding in tight spaces where standard welding helmets are limited in space. The mask is also detachable from the goggles, allowing for even more versatility.

#### 2 ARC SENSORS

2 arc sensors constantly monitor the arc, allowing for consistent shade control so you can focus on your welds.

#### TRUE COLOUR VIEW LENS TECHNOLOGY

Greatly improves the optics of your helmet, letting you see a full spectrum of colors.

#### ROOM FOR A RESPIRATOR

Designed to be worn with a Respirator, providing a filtration against odors, dust, all types of fumes, oil and water mists and micro-organisms.

#### UV/IR RAY PROTECTION

In combination with the Welding Hood, the Welding Goggles and Mask provide protection against UV/IR rays.

### CODE: RVRWX1000

Comes Complete With : Goggles & Mask , Welding Hood , Carry Bag , Head Band , Manual , 2 Outer lens , 1 Inner Lens , 2 Year Warranty



Detachable



True Color View



5-13 Shade Control



Sleep Mode



Digital Operation



2 ARC Sensors

\*LED LIGHT OPTIONAL



\*CARRY BAG